TX/XS650 CAM SHAFT SPROCKET SYSTEMS

MOTORCYCLE
M7-033

ENGINE STOP SWITCH

SET PART NUMBER	HANDLE SWITCH NO.	MODEL APPLICATION
444-W0087-10-00	437-83976-01-00	DT100A/B/C, DT175A/B/C, DT250A/B/C, DT360A, DT400B/C
	444-83975-01-00	DT125A/B/C
1E6-W0087-10-00	437-83976-02-00	DT100C, DT175C, DT250C, DT400C
	444-83975-02-00	DT125C
	1E6-83976-00-00	XT500C, XT500D

DIMMER SWITCH

SET PART NUMBER	HANDLE SWITCH NO.	MODEL APPLICATION
360-W0087-10-00	397-83973-02-00	RS100C, RD125B/C, RD250A/B
	397-83973-10-00	RD200A/B/C
	564-83973-00-00	XS650C
444-W0087-10-00	444-83972-03-00	DT125A/B/C
	498-83972-60-00	DT100C, DT250B, DT400B
	498-83972-61-00	DT175C, DT250C, DT400C
1E6-W0087-10-00	444-83972-04-00	DT125C
	498-83972-62-00	DT175C, DT250C, DT400C
	1E6-83972-00-00	DT250D, DT400D, XT500C
	1T2-83972-00-00	XT500D
	1T9-83910-00-00	DT100D
	558-83972-00-00	DT100C
1A0-W0087-10-00	564-83973-01-00	XS650C
	1A0-83973-01-00	RD400C/D, XS360C/D, XS500C/D
	1J7-83973-01-00	XS750D, XS750 2D
	1T3-83973-00-00	XS650D

SWITCH PART NO.	PRICE	
360-W0087-10-00 444-W0087-10-00 1A0-W0087-10-00 1E6-W0087-10-00 360-W0087-20-00 1A0-W0087-20-00 397-W0087-30-00		

Yamaha 650cc models are divided into two camshaft sprocket system groups. Each system has two different cam chain/chain joint combinations. Please alert parts and service personnel concerning identification, part numbers, and interchangeability.

MODEL XS1-XS1B-XS2-TX650
(1970 - 1973)

DESCRIPTION	PART NUMBER	REMARKS
Camshaft Assembly	256-12170-09-00	34T, See Note 3
Cam Chain Sprocket	256-11549-00-00	17T
Cam Chain	94610-01102	(102L) (I.D. "A")
Chain Joint	94610-01001	See Note 1
Cam Chain	94590-02102	(102L) (No I.D. marks)
Chain Joint	94690-02021	

MODEL GROUP TX650A-XS650B/C/D
(1974 - 1977)

DESCRIPTION	PART NUMBER	REMARKS
Camshaft Assembly	447-12170-00-00	36T
Cam Chain Sprocket	447-11549-01-00	18T
Cam Chain	94562-19106	(106L) (I.D. "DID" or "Japan")
Chain Joint	94652-19001	
Cam Chain	94500-02106	(108L) (I.D. "M")
Chain Joint	94600-02001	

INTERCHANGEABILITY

1) No chain joint is interchangeable with any other chain joint due to different pin diameters.
2) Cam chains are interchangeable in the same model group, but not between model groups.
3) Camshaft, sprocket, and chains for one model group are interchangeable with the same parts for the other model group, but only as a set.

NOTES:
1) Chain joint 94610-01001 will not be restocked after present stock is exhausted.
2) Camshaft assembly 256-12170-00-00 and 256-12170-01-00 requires the use of the following valve springs.

Qty	Part Number	Remarks
4	90501-29150	Inner spring
4	90501-46187	Outer spring

3) Camshaft assembly 256-12170-09-00 requires the use of the following valve springs:

4	90501-29284	Inner spring
4	90501-42288	Outer spring

©YAMAHA MOTOR CORPORATION, U. S. A., BUENA PARK, CALIFORNIA